Responsibility for Slab Curling

ASCC Position Statement #30

urling is the distortion of a slab into a curved shape by bending of the edges due to differences in moisture between the top and bottom of a concrete slab. It is caused primarily by loss of moisture from the concrete surface as the concrete dries. The moisture loss occurs in all environments at less than 100% relative humidity and is typically more severe in areas of low relative humidity.

The effect of curling on floor serviceability varies depending on the intended use. A curled slab may be serviceable when covered by carpet but not by vinyl tile. A curled slab may also experience joint deterioration when subjected to forklift traffic. "A Checklist for Industrial Floor Design" published in *Concrete International*, November 2001 includes a "crack and curl management" checklist to aid the designer in minimizing curling to suit the Owner's intended use.

Concrete contractors are responsible for initial floor flatness and levelness that is measured within 72 hours of placement, as required by ACI 117-06 and ACI 301-05. But flatness can change with time due to curl. "The Concrete Floor Tolerance/Floor Covering Conundrum" *Concrete International*, July 2003, includes two examples of measured floor flatness and levelness that decrease by as much as 50% in a year due to curling. Both the Canadian Standards Association (CSA) and the American Concrete Institute (ACI) recognize that control of curling is a designer responsibility.

CSA A23.1-04 "Concrete materials and methods of concrete construction" states:

6.4.2.2.3 Curling or warping

Owners shall specify low-shrinkage concrete mixes, appropriate curing, or suitable reinforcing, or a combination of these, as necessary to minimize curling to suit their intended usage.

<u>Commentary</u>: Tolerance losses up to 50% may occur in jointed floors due to normal drying shrinkage curling. Curling may also create material handling problems or produce a surface profile that is unsuitable for the application of subsequent finishes.

ACI 360R-06 "Design of Slabs-on-Ground" states:

- "Designers can take steps to reduce shrinkage cracking and curling through appropriate design and specifications." (Section 13.1)
- "Designers of enclosed slabs-on-ground can reduce shrinkage cracking and shrinkage curling by considering features that affect these phenomena. The following checklist indicates factors that should be addressed." (Section 13.5)
- "Design methods are given for unreinforced concrete, reinforced concrete, shrinkage-compensating concrete, post-tensioned concrete, fiber reinforced concrete slabs-on-ground, and slabson-ground in refrigerated buildings, followed by information on shrinkage and curling problems. Advantages and disadvantages of each of these slab designs are provided, including the ability of some slab designs to minimize cracking and curling more than others." (Foreword)

Unreinforced jointed slabs are the most common slab-on-ground designs. ACI 360R-06, Table 2.2, states that with this design "flatness and levelness may decrease with time." Owners should be advised of this disadvantage for this slab design.

Because design and specifications minimize curling to suit the Owner's use, concrete contractors will assist the designer in meeting the Owner's objectives by complying with Division 3 specifications and project drawings. For more information on curling see "Why Slabs Curl: Part I and II", *Concrete International*, March and April 2002.

If you have any questions, contact your ASCC concrete contractor or the ASCC Technical Hotline at (800) 331-0668.



2025 S. Brentwood Blvd., Suite 105 St. Louis, MO 63144
Telephone: 314-962-0210 Website: www.ascconline.org
Toll Free: 866-788-2722 E-mail: ascc@ascconline.org